




Stepper Motor Drivers



Stepper Motor Drivers



Stepper Motor Drivers





Stepper Motor Drivers

50-Pin Cable Plug


J	Y1	1
	Y2	2
	Y3	3
	Y4	4
	Y5	5
	Y6	6
	Y7	7
7	Y8	8
	GND	9

J	X1: X_se	1
	X2: Y_se	2
	X3: Z_se	3
	X4: Cutter	4
8	X5	5
	X6	6
	X7	7
	X8	8
	24V+	9
	GND	10
	Shield	11


J	24V+	1
10	GND	2




X_AXIS




Y_AXIS



Z_AXIS



A/C_AXIS



Spindle Motor

